

**Illinois Commerce Commission  
Pipeline Safety  
Exit Meeting Documentation Form**

<b>Operator:</b>	AMEREN ILLINOIS COMPANY
<b>Inspection Unit(s):</b>	Sciota Storage
<b>Date of Meeting:</b>	05/03/2016
<b>Pipeline Safety Analyst:</b>	Jim Watts
<b>Exit Meeting Contact:</b>	Joe Orsa

**Exit Statement**

**INSPECTION FINDINGS**

**Standard Inspection - Record Audit**

**Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

**2012-S001-00018** (Code Part [192.707]) - Ameren has replaced all of the pipeline line markers at Sciota Storage and now include the current operator contact information.

**2013-S001-00030** (Code Part [192.471(a)]) - The test lead at well SM-34 has been corrected and indicated a potential level of -.970v taken by Ameren field personnel on 11-3-2014. Due to the corrective actions taken by Ameren, the outstanding issue 2012-S001-00018 can be recorded as closed.

**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Notice of Violations(s) Corrected:**

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:

James Watts

Operator Representative Signature:

Joe Orsa